

Sun StorEdge[™] 5310 NAS Appliance Release Notes

Sun Microsystems, Inc. www.sun.com

Part No. 819-0883-10 January 2005, Revision A

Submit comments about this document at: $\verb|http://www.sun.com/hwdocs/feedback| \\$

Copyright 2005 Sun Microsystems, Inc., 4150 Network Circle, Santa Clara, California 95054, U.S.A. All rights reserved.

Sun Microsystems, Inc. has intellectual property rights relating to technology that is described in this document. In particular, and without limitation, these intellectual property rights may include one or more of the U.S. patents listed at http://www.sun.com/patents and one or more additional patents or pending patent applications in the U.S. and in other countries.

This document and the product to which it pertains are distributed under licenses restricting their use, copying, distribution, and decompilation. No part of the product or of this document may be reproduced in any form by any means without prior written authorization of Sun and its licensors, if any.

Third-party software, including font technology, is copyrighted and licensed from Sun suppliers.

Parts of the product may be derived from Berkeley BSD systems, licensed from the University of California. UNIX is a registered trademark in the U.S. and in other countries, exclusively licensed through $X/Open\ Company$, Ltd.

 $Sun, Sun\,Microsystems, the\,Sun\,logo,\,AnswerBook2,\,docs.sun.com,\,Sun\,StorEdge,\,Java,\,and\,Solaris\,are\,trademarks\,or\,registered\,trademarks\,of\,Sun\,Microsystems,\,Inc.\,in\,the\,U.S.\,and\,in\,other\,countries.$

Mozilla, Netscape, and Netscape Navigator are trademarks or registered trademarks of Netscape Communications Corporation in the United States and other countries.

All SPARC trademarks are used under license and are trademarks or registered trademarks of SPARC International, Inc. in the U.S. and in other countries. Products bearing SPARC trademarks are based upon an architecture developed by Sun Microsystems, Inc.

The OPEN LOOK and SunTM Graphical User Interface was developed by Sun Microsystems, Inc. for its users and licensees. Sun acknowledges the pioneering efforts of Xerox in researching and developing the concept of visual or graphical user interfaces for the computer industry. Sun holds a non-exclusive license from Xerox to the Xerox Graphical User Interface, which license also covers Sun's licensees who implement OPEN LOOK GUIs and otherwise comply with Sun's written license agreements.

U.S. Government Rights—Commercial use. Government users are subject to the Sun Microsystems, Inc. standard license agreement and applicable provisions of the FAR and its supplements.

DOCUMENTATION IS PROVIDED "AS IS" AND ALL EXPRESS OR IMPLIED CONDITIONS, REPRESENTATIONS AND WARRANTIES, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT, ARE DISCLAIMED, EXCEPT TO THE EXTENT THAT SUCH DISCLAIMERS ARE HELD TO BE LEGALLY INVALID.

Copyright 2005 Sun Microsystems, Inc., 4150 Network Circle, Santa Clara, California 95054, Etats-Unis. Tous droits réservés.

Sun Microsystems, Inc. a les droits de propriété intellectuels relatants à la technologie qui est décrit dans ce document. En particulier, et sans la limitation, ces droits de propriété intellectuels peuvent inclure un ou plus des brevets américains énumérés à http://www.sun.com/patents et un ou les brevets plus supplémentaires ou les applications de brevet en attente dans les Etats-Unis et dans les autres pays.

Ce produit ou document est protégé par un copyright et distribué avec des licences qui en restreignent l'utilisation, la copie, la distribution, et la décompilation. Aucune partie de ce produit ou document ne peut être reproduite sous aucune forme, par quelque moyen que ce soit, sans l'autorisation préalable et écrite de Sun et de ses bailleurs de licence, s'il y ena.

Le logiciel détenu par des tiers, et qui comprend la technologie relative aux polices de caractères, est protégé par un copyright et licencié par des fournisseurs de Sun.

Des parties de ce produit pourront être dérivées des systèmes Berkeley BSD licenciés par l'Université de Californie. UNIX est une marque déposée aux Etats-Unis et dans d'autres pays et licenciée exclusivement par X/Open Company, Ltd.

Sun, Sun Microsystems, le logo Sun, AnswerBook2, docs.sun.com, Sun StorEdge, Java, et Solaris sont des marques de fabrique ou des marques déposées de Sun Microsystems, Inc. aux Etats-Unis et dans d'autres pays.

Mozilla, Netscape, et Netscape Navigator sont des marques de Netscape Communications Corporation aux Etats-Unis et dans d'autres pays.

Toutes les marques SPARC sont utilisées sous licence et sont des marques de fabrique ou des marques déposées de SPARC International, Inc. aux Etats-Unis et dans d'autres pays. Les produits portant les marques SPARC sont basés sur une architecture développée par Sun Microsystems, Inc.

L'interface d'utilisation graphique OPEN LOOK et Sun[™] a été développée par Sun Microsystems, Inc. pour ses utilisateurs et licenciés. Sun reconnaît les efforts de pionniers de Xerox pour la recherche et le développement du concept des interfaces d'utilisation visuelle ou graphique pour l'industrie de l'informatique. Sun détient une license non exclusive de Xerox sur l'interface d'utilisation graphique Xerox, cette licence couvrant également les licenciées de Sun qui mettent en place l'interface d'utilisation graphique OPEN LOOK et qui en outre se conforment aux licences écrites de Sun.

LA DOCUMENTATION EST FOURNIE "EN L'ÉTAT" ET TOUTES AUTRES CONDITIONS, DECLARATIONS ET GARANTIES EXPRESSES OU TACITES SONT FORMELLEMENT EXCLUES, DANS LA MESURE AUTORISEE PAR LA LOI APPLICABLE, Y COMPRIS NOTAMMENT TOUTE GARANTIE IMPLICITE RELATIVE A LA QUALITE MARCHANDE, A L'APTITUDE A UNE UTILISATION PARTICULIERE OU A L'ABSENCE DE CONTREFAÇON.





Contents

System Requirements 1

Known Issues 2

Release Documentation 5

Service Contact Information 5

Sun StorEdge 5310 NAS Appliance Release Notes

This document contains important information about the Sun StorEdge[™] 5310 NAS Appliance that was not available at the time the product documentation was published. Read this document so that you are aware of issues or requirements that can impact the installation and operation of the Sun StorEdge 5310 NAS Appliance.

- "System Requirements" on page 1
- "Known Issues" on page 2
- "Release Documentation" on page 5
- "Service Contact Information" on page 5

Important – The system supports only a single administrative login at one time.

System Requirements

The Sun StorEdge 5310 NAS Appliance system ships with the Web Administrator software already installed. You do not need to install any software to manage the Sun StorEdge 5310 NAS Appliance.

To access the Web Administrator management interface, you must have a network-attached computer running one of the following browsers. You must use a JavaTM technology-enabled browser with Java Plug-In 1.3.1 (or later).

- Internet Explorer
- Mozilla[™]
- Netscape Navigator[™]

Known Issues

- A 4 port HA bond does not fail-over to another port.
 - Workaround Sun recommends you use 2 port HA bonding because the high availability is just used for redundancy.
- The Notification Email URL field shows the hostname URL, and you may not connect to the Web Administrator by clicking this URL.
 - Workaround If the DNS does not resolve the hostname, use the IP address to connect to the Sun StorEdge 5310 NAS Appliance.
- LCD displays "_" for over two minutes while booting.
 - Workaround This is not a problem, the NAS will boot properly.
- Help contents in the Web Administrator include RAID management topics.
 - Workaround In-band RAID management from the Sun StorEdge 5310 NAS Appliance Web Administrator is not supported in this product. Ignore these topics.
- In rare cases the log shows a message !utm_scsi_write: lun=31, which may or may not indicate a real problem.
 - Workaround If this message is followed by other critical hardware errors then they must be addressed accordingly; otherwise you can safely ignore the message.
- HA and Port aggregation bond IP address may not restore properly after you delete a bond.
 - Workaround Select a different IP address for the bond.
- The Sun StorEdge 5310 NAS Appliance Web Administrator is either slow or hangs on a PC running W2K and Solaris with Mozilla.
 - Workaround Kill the Sun Stor Edge 5310 NAS Appliance Web Administrator browser session using the:
 - task manager (in Microsoft Windows)

■ UNIX kill command (on Solaris/Linux)

Then restart your Web Administrator browser session.

■ Poor RX/TX optical signal strength may result in degraded performance.

Workaround - If there are no other critical hardware errors and you see significant performance degradation, this degradation could be related to fibre channel link errors. You need to contact service (see "Service Contact Information" on page 5).

■ Occasionally the Sun StorEdge 5310 NAS Appliance Web Administrator display for promote volume list [file replicator] may be incorrect [stale information].

Workaround - In order to refresh, log out and log back in on the Web Administrator.

■ Creating Volumes from the Sun StorEdge 5310 NAS Appliance Web Administrator using Gb causes a rounding error.

Workaround - This is just a display error and no space is really lost. Ignore this error message.

Sun StorEdge 5310 NAS Appliance Web Administrator interface reports incorrect Voltage Regulator values, occasionally causing erroneous visual alerts.

Workaround - This is a false error indication and there is nothing wrong in the system functionality. Ignore this error message.

■ Under rare circumstances when the fault LED of the CSM is lit, the Sun StorEdge 5310 NAS Appliance event log shows the generic sysmon ...unknown battery status error.

Workaround - The CSM module needs service attention and may not necessarily be a battery problem.

■ While running I/Os occasional disk and/or fibre channel errors may cause some volumes to be marked Read-Only. It is possible that volume-related operations on the Read-Only volume may hang, including the Diagnostic Email. However the I/O to the other volumes continues as normal

Workaround - If this is a correctable error, a reboot of the Sun StorEdge 5310 NAS Appliance will fix the Read-Only issue. If there is a real critical hardware error as shown in the event log, then that must be addressed with an escalation to the service (see "Service Contact Information" on page 5).

■ When a RAID volume goes critical on a 5310EU F because the existing HotSpares are used, service needs to be engaged to bring the additional HotSpares online (see "Service Contact Information" on page 5).

- On a CSM RAID controller hardware failure, if the controller is pulled out with active I/Os it causes volumes to go Read-Only.
 - Workaround Please engage service (see "Service Contact Information" on page 5) before making an attempt to replace the controller hardware.
- The Compliance option shows up in the Web Administrator under Create File Volumes.

Workaround - Compliance Archiving Software is not supported in this release. Creating a file volume with this option "checked" from the Web Administrator will successfully create the volume, but the log shows an error message *Enable compliance failed. This error message can* be safely ignored, bu Sun recommends not using this compliance checkbox while creating the file volume.

Release Documentation

The following documentation is included with this release:

Setting Up the Sun StorEdge 5310 NAS Appliance (setup poster)

The remaining documentation is posted on the documentation Web site at:

http://www.sun.com/products-n-solutions/hardware/docs/Network_Storage_Solutions/storage_appliances/index.html

The remaining documentation includes:

Sun StorEdge 5310 NAS Appliance Quick Reference Manual Sun StorEdge 5310 NAS Appliance Hardware Installation, Configuration, and User Guide Sun StorEdge 5310 NAS Appliance Software Installation, Configuration, and User Guide Sun StorEdge 5310 NAS Appliance Safety and Compliance Guide Sun StorEdge 5300 RAID Expansion Unit and Sun StorEdge 5300 Expansion Unit F Safety and Compliance Guide

Service Contact Information

If you need help installing or using this product, call 1-800-USA-4SUN, or go to:

http://www.sun.com/service/contacting/index.html